

**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Phone (306) 653-6600 Fax: (306) 242-5599

**- Site Service Report -**

March 12, 2007

**IRD SO#: 10407A****IRD Ref: 10407AW****From: Jeff Wourms****To: ESS****Project Name: IL LTPP iSINC Data Collection****Project Location: I-57 NB MM 125.7****Service Date(s): January 17, 2007****Weather:**

**Job Description:** Diagnose problem with #2 bending plate. IRD Saskatoon dialed into site & checked waveforms, BP#2 appears to be all over the place (excessive noise on signal).

**Work Completed:** Disconnect connection from front of iSINC and test resistance of both plates.  
Open pull-box in shoulder to check for possible wire damage &/or splices, everything looked OK.  
See attached electrical readings.

**Work Remaining:** Replace bending plate #2.

**Parts Used:** N/A

**Mileage / Travel Time:** 270 Miles

**Time Spent on Site:** 6

**Notes:**

**Action Items:**

Item	Action Required	Ownership
1.	Replace Bending Plate #2	Field Staff / ESS